ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 7 | Byatarayanapura |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0437 | NA | Amruthahalli |
| **Segment No.** | **Total Length (m)** | |
| 7/S-W0437/S035439 | 124.44 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 124.44 | 77.602735 | 13.065452 | 77.603104 | 13.064612 | W0392 | W0431 |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements of roads and drains in Amruthahalli A.Manjunath House road in S.C Colony Amruthahalli in Ward No 07, Byatarayanapura | 2950000 | 2015-16 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2015 - 2016 | Road | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | 1.Providing and laying wet mix.2.Providing and laying SDBC. | 007-15-000048 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/278/15-16 | 03/03/2016 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 19/09/2018 | 18/09/2020 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| A.Manjunath | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9845890399 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | Pushpalatha.N.D |
| **Date of Inspection** | **Remarks** | |
| 19/09/2018 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition |  | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition |  | This photo seems out of range. |
| Road Condition |  | This photo seems out of range. |
| Road Condition |  | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | R.L.Parameshwaraiah | 27/09/2018 | 19/10/2018 | Approved |

| | | | | |
|---|---|---|---|---|
| SE | Vasu K M | 27/09/2018 | 19/10/2018 | Completed |
| EE | Mohandas H.T | 19/09/2018 | 19/10/2018 | completed |
| AEE | H.Ranganath | 19/09/2018 | 19/10/2018 | Verified |
| AE | Pushpalatha.N.D | 19/09/2018 | 19/10/2018 | Mobile Verification Done |
| AE | Pushpalatha.N.D | 19/09/2018 | 19/10/2018 | Forwarded |